Release Notes

WWAN module MC7455 02.38.00.00

Table of contents

02	1.	Preface
02	2.	Backing up the current configuration
03	3.	New features, modifications, and history
03		WWAN module firmware improvements 02.38.00.00
03		WWAN module firmware improvements 02.33.03.00
03		WWAN module firmware improvements 02.32.11.01
03		WWAN module firmware improvements 02.30.01.01
03		WWAN module firmware improvements 02.24.05.06

04 4. General advice



1. Preface

In the context of the hardware given by the products the at a time latest WWAN module firmware is available for all LANCOM products with appropriate WWAN module and is available free of charge for dowload from LANCOM Systems.

This document describes the innovations within the WWAN module MC7455 02.38.00.00, as well as the improvements since the previous release.

Before upgrading the firmware, please pay close attention to chapter 3 "General advice" of this document.

2. Backing up the current configuration

Please install the latest LANtools version first.

Before upgrading your LANCOM devices to a new WWAN firmware version it is essential to backup the configuration data!

After that you can use LANconfig to load the latest LCOS-version into the device.

Due to extensive features it is not possible to downgrade to a previous firmware without using the backup configuration.

If you want to upgrade devices which are only accessible via router connections or Wi-Fi bridges, please keep in mind to upgrade the remote device first and the local device afterwards.

We strongly recommend updating productive systems only after internal tests in client environment. Despite intense internal and external quality assurance procedures possibly not all risks can be eliminated by LANCOM Systems.



WWAN module firmware improvements 02.38.00.00

Bugfixes / improvements

→ General functional and stability improvements

WWAN module firmware improvements 02.33.03.00

Bugfixes / improvements

→ General stability improvements

WWAN module firmware improvements 02.32.11.01

Bugfixes / improvements

→ General stability improvements

WWAN module firmware improvements 02.30.01.01

Bugfixes / improvements

- \rightarrow Optimization of the NMEA data transmission
- \rightarrow General functional and stability improvements

WWAN module firmware improvements 02.24.05.06

Bugfixes / improvements

- \rightarrow Performance improvements
- \rightarrow General functional and stability improvements



4. General advice

Disclaimer

LANCOM Systems GmbH does not take any guarantee and liability for software not developed, manufactured or distributed by LANCOM Systems GmbH, especially not for shareware and other extraneous software.



LANCOM Systems GmbH Adenauerstr. 20/B2 52146 Wuerselen | Germany info@lancom.de www.lancom-systems.com LANCOM, LANCOM Systems, LCOS, LANcommunity and Hyper Integration are registered trademarks. All other names or descriptions used may be trademarks or registered trademarks of their owners. This document contains statements relating to future products and their attributes. LANCOM Systems reserves the right to change these without notice. No liability for technical errors and/or omissions. 10/22